

Telephone: +44 (0)113 259 1999

Email: <a href="mailto:info@bttg.co.uk">info@bttg.co.uk</a>
Website: <a href="mailto:www.bttg.co.uk">www.bttg.co.uk</a>

Date: 25 October 2018

Our Ref: 55632-1 Your Ref: -

Page: 1 of 4

Client: Flint Hire & Supply Limited

Unit 9 Deptford Trading Estate

Blackhorse Road

London SE8 5HY

Job Title: Surface Ignition Of Curtains & Drapes

Client's Order No:

Date of Receipt: 18 October 2018
Date of Test Start: 23 October 2018

Description of Sample(s): One sample identified as follows was received for testing:

Heavy Cotton Canvas Non FR, 36" wide, 468g/m2

Work Requested: We were asked to make the following test:

BS 5867: Part 2: 2008 (2015): Type B Curtains, Drapes and Blinds





Telephone: +44 (0)113 259 1999 Email: info@bttg.co.uk Website: www.bttg.co.uk

Date: 25 October 2018

**Our Ref:** 55632-1 Your Ref:

Page: 2 of 4

#### Flint Hire & Supply Limited

Sample was identified as follows:

Heavy Cotton Canvas Non FR, 36" wide, 468g/m2

# BS 5867: Part 2: 2008 (2015): Type B Curtains, Drapes and Blinds Testing as received.

Three specimens from both length and width were tested in accordance with BS EN ISO 15025: Procedure A (surface ignition): 2002. The sample was tested at 24°C and 47 % relative humidity (R.H.).

Each specimen was subjected to an applied flame using propane and a 15 second flame application time. The results obtained (shown in the table below) were assessed according to the requirements of BS 5867: Part 2: 2008 (2015).

### Pre-treatment

If the fabric is a pass in the 'as received' condition then the fabric is subjected a water soak procedure as specified in BS EN 1021: Annex D: 2006.

### Testing after pre-treatment

Three specimens, after pre-treatment, from both length and width were tested following the procedure described above.

Test results relate only to the sample tested.

The results for all tests are given in the table(s) on the following page(s).

Reported by:... B Bland

Fire Technician

Countersigned By:.

P Doherty

Operational Head

Enquiries concerning this report should be addressed to Customer Services.





Telephone: +44 (0)113 259 1999

Email: info@bttg.co.uk Website: www.bttg.co.uk

Date: 25 October 2018

Our Ref: 55632-1 Your Ref: -

Page: 3 of 4

# Flint Hire & Supply Limited

# **RESULTS**

Sample Ref: Heavy Cotton Canvas Non FR, 36" wide, 468g/m2

# BS 5867: Part 2: 2008 (2015): Type B Curtains, Drapes and Blinds

**Testing as Received** 

	Length			Width		
Specimen No.	1	2	3	4	5	6
Flame reached an edge	No	No	No	No	No	No
Hole reached an edge	No	No	No	No	No	No
Flaming debris separated	No	No	No	No	No	No

#### Requirements

Any "Yes" means fail except if only one specimen fails a further 6 specimens are tested, if the second 6 specimens all pass the result is a pass.

# Result in `as received`: Pass

Testing after pre-treatment

		Length			Width		
Specimen No.	1	2	3	4	5	6	
Flame reached an edge	No	No	No	No	No	No	
Hole reached an edge	No	No	No	No	No	No	
Flaming debris separated	No	No	No	No	No	No	

### Requirements

Any "Yes" means fail except if only one specimen fails a further 6 specimens are tested, if the second 6 specimens all pass the result is a pass.

# Result in `after pre-treatment`: Pass





Telephone: +44 (0)113 259 1999

Email: <u>info@bttg.co.uk</u> Website: <u>www.bttg.co.uk</u>

Date: 25 October 2018

Our Ref: 55632-1 Your Ref: -

Page: 4 of 4

#### **Flint Hire & Supply Limited**

#### Conclusion

The fabric meets the Type B performance requirements of BS 5867: Part 2: 2008 (2015).

This report relates only to the samples submitted and as described in the report.

This material should be identified with the manufacturers name, trademark or other identifying mark, the statement 'Flammability complies with the requirements of BS 5867: Part 2: Type B and instructions of any special precautions to be taken concerning care (including cleansing) of the curtain, drape or window blind to be manufactured from the fabric, preferably using an appropriate care labelling symbol in accordance with BS EN 23758 and taking account of the pre-treatment using in this test and the requirements of Clause 4 of BS 5867: Part 2: 2008 (2015). If the fabric is unsuitable for cleansing, this shall be stated.

#### **Uncertainty Budget**

There is no uncertainty budget associated with BS 5867: Part 2: Type B as no measurements are determined, the pass/fail criteria is assessed visually.

